


Amp.	Poles	pack. unit	110V~	230V~	400V~	500V~	>50-500V~	>50-500V~
			Cat.No.	Cat.No.	Cat.No.	Cat.No.	Cat.No.	Cat.No.
flange 75 x 75 - fixing center 60 x 60								
16	3	10	313-4f7	313-6f7	313-9f7	313-7f7	313-10f7	313-2f7
16	4	10	314-4f7	314-9f7	314-6f7	314-7f7	314-10f7	314-2f7
16	5	10	315-4f7	315-9f7	315-6f7	315-7f7	315-10f7	315-2f7
32	3	10	323-4f7	323-6f7	323-9f7	323-7f7	323-10f7	323-2f7
32	4	10	324-4f7	324-9f7	324-6f7	324-7f7	324-10f7	324-2f7
32	5	10	325-4f7	325-9f7	325-6f7	325-7f7	325-10f7	325-2f7



315-6f7

Amp.	Poles	pack. unit	110V~	230V~	400V~
			Cat.No.	Cat.No.	Cat.No.
flange 75 x 75 - fixing center 60 x 60					
16	3	10	313-4TTf7	313-6TTf7	313-9TTf7
16	4	10	314-4TTf7	314-9TTf7	314-6TTf7
16	5	10	315-4TTf7	315-9TTf7	315-6TTf7
32	3	10	323-4TTf7	323-6TTf7	323-9TTf7
32	4	10	324-4TTf7	324-9TTf7	324-6TTf7
32	5	10	325-4TTf7	325-9TTf7	325-6TTf7

TURBO TWIST
click



313-6TTf7

Amp.	Poles	pack. unit	110V~	230V~	400V~	500V~	>50-500V~	>50-500V~
			Cat.No.	Cat.No.	Cat.No.	Cat.No.	Cat.No.	Cat.No.
flange 75 x 75 - fixing center 60 x 60								
16	3	10	3132-4	3132-6	3132-9	3132-7	3132-10	3132-2
16	4	10	3142-4	3142-9	3142-6	3142-7	3142-10	3142-2
16	5	10	3152-4	3152-9	3152-6	3152-7	3152-10	3152-2
32	3	10	3232-4	3232-6	3232-9	3232-7	3232-10	3232-2
32	4	10	3242-4	3242-9	3242-6	3242-7	3242-10	3242-2
32	5	10	3252-4	3252-9	3252-6	3252-7	3252-10	3252-2



3152-6

Amp.	Poles	pack. unit	110V~	230V~	400V~
			Cat.No.	Cat.No.	Cat.No.
flange 75 x 75 - fixing center 60 x 60					
16	3	10	3132-4TT	3132-6TT	3132-9TT
16	4	10	3142-4TT	3142-9TT	3142-6TT
16	5	10	3152-4TT	3152-9TT	3152-6TT
32	3	10	3232-4TT	3232-6TT	3232-9TT
32	4	10	3242-4TT	3242-9TT	3242-6TT
32	5	10	3252-4TT	3252-9TT	3252-6TT

TURBO TWIST
click



3132-6TT

