

Диапазоны

мбар	бар	кПа	МПа	кг/см ²	мм H ₂ O	см H ₂ O	дюйм H ₂ O	psi	mm Hg	in. Hg
MB	BR	KP	MP	KSC	MMW	CMW	IW	PSI	MMHG	INHG
16	0,06	1,6	0,01	0,06	160	16	6	1	12	0,5
25	0,1	2,5	0,016	0,1	250	25	10	1,5	20	0,8
40	0,16	4	0,025	0,16	400	40	15	2,5	30	1,2
60	0,25	6	0,04	0,25	600	60	25	4	50	1,6
100	0,4	10	0,06	0,4	1000	100	40	6	75	3
160	0,6	16	-0,01/0	0,6	1600	160	60	8	125	5
250	-0,06/0	25	-0,016/0	-0,06/0	2500	250	100	-1/0	200	8
400	-0,1/0	40	-0,025/0	-0,1/0	4000	400	150	-1,5/0	300	12
600	-0,16/0	60	-0,04/0	-0,16/0	6000	600	250	-2,5/0	500	16
-16/0	-0,25/0	-1,6/0	-0,06/0	-0,25/0	-160/0	-16/0	-6/0	-4/0	-12/0	-0,5/0
-25/0	-0,4/0	-2,5/0	-0,012/0,012	-0,4/0	-250/0	-25/0	-10/0	-6/0	-20/0	-0,8/0
-40/0	-0,6/0	-4/0	-0,02/0,02	-0,6/0	-400/0	-40/0	-15/0	-8/0	-30/0	-1,2/0
-60/0	-0,05/0,05	-6/0	-0,03/0,03	-0,05/0,05	-600/0	-60/0	-25/0	-1,25/1,25	-50/0	-1,6/0
-100/0	-0,08/0,08	-10/0		-0,08/0,08	-1000/0	-100/0	-40/0	-2/2	-75/0	-3/0
-160/0	-0,125/0,125	-16/0		-0,125/0,125	-1600/0	-160/0	-60/0	-3/3	-125/0	-5/0
-250/0	-0,2/0,2	-25/0		-0,2/0,2	-2500/0	-250/0	-100/0	-4/4	-200/0	-8/0
-400/0	-0,3/0,3	-40/0		-0,3/0,3	-4000/0	-400/0	-150/0		-300/0	-12/0
-600/0		-60/0			-6000/0	-600/0	-250/0		-500/0	-16/0
-8/8		-0,8/0,8			-80/80	-8/8	-5/5		-10/10	-0,25/0,25
-12,5/12,5		-1,25/1,25			-125/125	-12,5/12,5	-8/8		-16/16	-0,4/0,4
-20/20		-2/2			-200/200	-20/20	-12,5/12,5		-25/25	-0,6/0,6
-30/30		-3/3			-300/300	-30/30	-20/20		-40/40	-0,8/0,8
-50/50		-5/5			-500/500	-50/50	-30/30		-60/60	-1,5/1,5
-80/80		-8/8			-800/800	-80/80	-50/50		-100/100	-2,5/2,5
-125/125		-12,5/12,5			-1250/1250	-125/125	-75/75		-160/160	-4/4
-200/200		-20/20			-2000/2000	-200/200	-125/125		-250/250	-6/6
-300/300		-30/30			-3000/3000	-300/300				-8/8

Другие диапазоны и единицы измерения по запросу